

General Environmental Incident Summary

Incident: 2067 **Date/Time Notice:** 10/11/2013 1810 **DEM Incident No:**
Responsible Party: ONEOK Rockies Midstream
Date Incident: 10/10/2013 **Time Incident:** 1730 **Duration:** 1 minutes
County: Williams **Twp:** 155 **Rng:** 102 **Sec:** 10 **Qtr:** NE
Lat: 48.26917 **Long:** -103.77910 **Method:** Navigation quality GPS
Location Description: Stateline Compressor Station address: 14312 59th Street NW, Williston, ND 58801

Submitted By: Mitch Anderson **Affiliation:**
Address:
City: **State:** **Zip:**

Received By:

Contact Person: Mitch Anderson
2700 Lincoln Avenue SE
Sidney, MT 59270

Distance Nearest Occupied Building: 1 Miles

Type of Incident: Tank Overflow

Description of Released Contaminant: Natural Gas Liquids

Volume Spilled: 200.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

Power Fuels was transferring natural gas liquids from their tanker truck to a 400 bbl mix tank at Stateline Compressor Station. While unloading his truck the driver overfilled the tank causing a spill. The entire contents of the spill was completely contained inside the secondary containment structure.

Risk Evaluation:

There were no immediate health hazards associated with this incident.

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 01 - air

Potential Environmental Impacts:

There were no adverse impacts to any surface waters, ground water or soils.

Action Taken or Planned:

The liquids were promptly pumped out of the containment and the tank was steam cleaned.

Wastes Disposal Location: The recovered liquid waste was pumped into an adjacent steel tank.

Agencies Involved: Local Emergency Manager

Updates

Date: 10/11/2013 ***Status:*** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Volume:

Notes:

Release into secondary containment. Reported to be cleaned up immediately. Please visit and verify the containment.

Date: 10/15/2013 ***Status:*** Reviewed - Assigned to Other Agency

Author: Miller, Adam

Updated Volume:

Notes:

I drove around the location and saw no evidence of a release off site. It appears as if clean up was sufficient.